

Oakwood Park HOA Mailbox Standards

The following will serve as the standard for mailboxes and mailbox repairs within the Oakwood Park HOA.

1. Mailboxes and posts are to be like kind to the original mailboxes installed in the community. The post is to be the old “Dicken’s” style post, with decorative support bracket under and supporting the mailbox. The acceptable support bracket is the “Bird of Paradise” Corner bracket, Model # 2060 from Action Ironworks and may be seen below or at:
http://webhosting.web.com/imagelib/sitebuilder/misc/show_image.html?linkedwidth=560&linkpath=http://www.actioniron.com/sitebuildercontent/sitebuilderpictures/Mailstands/.pond/Iron_Columns.jpg.w560h597.jpg&target=_self
2. The mailboxes may be of two alternative sizes, as follows:
 - a. Length 20”; Width 7”; Height 9”, the “Standard Box”, or
 - b. Length 22”; Width 8.5”; Height 10.5” the “Larger Box”
3. The brand of the mailbox shall be:
 - a. Gibraltar Model E1100B00 for the standard box, or Model E1600B00 for the larger box, or
 - b. Fulton Corporation Mailboxes from Houston Ironworks in Nesbit or the Glass Menagerie in Hernando.
4. The paint on both the mailbox and post shall be antique black (black with green).
5. The numbers shall be 2.5” with an italic font with NO background, placed behind the flag on the right side; more centered on the left side of the box. The numbers may be obtained from Brighter Boxes, Brock Shafer, contact information below.

The approved replacement contractor for mailboxes in the community is Brighter Boxes, Brock Shafer who may be reached at 901-238-7974, or shaferbrock@yahoo.com.

Illustrations and samples of the standards are included on the following page.

Alternatives may be considered, but only by application to the Architectural Review Committed upon the standard application form of the OWP HOA.

